United States
Department of the Interior
Bureau of Land Management

ORIGINAL

FIELD NOTES

OF
THE DEPENDENT RESURVEY OF

A PORTION OF

THE SOUTH BOUNDARY AND A

PORTION OF THE

SUBDIVISIONAL LINES, AND

THE SUBDIVISION OF SECTIONS 10, 11, 15, 23, 26, AND 34,

IN

TOWNSHIP 10 SOUTH, RANGE 4 WEST

OF THE SALT LAKE MERIDIAN
IN THE STATE OF UTAH

EXECUTED BY

M. Ross Workman Supervisory Cadastral Surveyor

Under special instructions dated August 1, 1996, approved August 23, 1996, which provided for the surveys included under Group Number 851, and assignment instructions dated August 23, 1996.

Survey commenced September 25, 1996

Survey completed September 9, 1997

INDEX DIAGRAM

Township 10 South, Range 4 West

			n, kange 4 w		
6	5	4	3	2	1
7	8	9 9	10 6 9	11 3 6	12
18	17	16	15 5 8	14	13
19	20	21	22 5	23 4	24
30	29	28	27 4 7	26 4	25
31	32	7 33		35	36

The	Subdivision	of	Section	10Page	9
The	Subdivision	of	Section	11Page	11
				15Page	
The	Subdivision	of	Section	23Page	14
The	Subdivision	of	Section	26Page	15
				34	

TOWNSHIP 10 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH

	His	tory of Surv	eys	
	Surveyed by		Retr. or Resurveyed	by
NORTH B Portion Portion Portion Portion	OUNDARY		·	•
Portion	A.D. Ferron	1871		
Portion	J. Gorlinski	1872	J. Gorlinski	1872
Portion	H.W. Miller and	1915	H.W. Miller and	1915
	I. Hayes	4710	I. Hayes	1713
Portion			G.B. Hatch	1966
SOUTH BO	OUNDARY (Second Stand	lard Parallel		
All Portion Portion Portion	J. Gorlinski	1872		
Portion	J. Colimbai	10/2	G.B. Hatch	1966
Portion			G.B. Hatch	1968
Portion			R. K. Baugh	1996-199
EAST BOU	JNDARY			
All	J. Gorlinski	1872		
Portion			J.C. Thoma	1917
All	!		G. B. Hatch	1966
Portion			M. Krohn	1989
WEST BO	UNDARY			
WEST BO Portion Portion Portion	J. Gorlinski	1874		
Portion	A.J. Stookey	1908	A.J. Stookey	1908
Portion		-700	H.W. Miller	1915
	!		I. Hayes	1710
SUBDIVIS	ION			
Portion	A.D. Ferron	1871		
Portion	J. Gorlinski	1874	J. Gorlinski	1874
Portion	H.W. Miller and	1915	H.W. Miller and	1915
	I. Hayes		I. Hayes	_
Portion			G.B. Hatch	1966
Portion			G.B. Hatch	1968

Group No. 851, Utah.

TOWNSHIP 10 SOUTH, RANGE 4 WEST, SALT LAKE MERIDIAN, UTAH

CHAINS

Preliminary to the resurvey, a diligent search was made for all corners. Identified corners were remonumented in their original positions; lost corners were restored and monumented at proportionate positions based on the original record. Coordinates for each corner were determined by Global Positioning System (G.P.S.) using relative positioning techniques. True bearings and distances were determined by inversing between the coordinates.

The geographic position of the corner of sections 34 and 35, T. 10 S., R. 4 W., which will also function as a B.L.M. control station, was determined by a tie to U.S.G.S. triangulation station "MAPLE2", by the Global Positioning System, using relative positioning techniques, is as follows:

Latitude 39° 54' 15.543" N. Longitude 112° 16' 15.010" W. N.A.D. 1983.

The mean magnetic declination as projected from the U.S. Geological Survey Magnetic Declination Map of 1990, is 13 3/4° E.

Dependent Resurvey of a Portion of the South Boundary, (Second Standard Parallel South), T. 10 S., R. 4 W., Salt Lake Meridian, Utah

Reestablishment of the Survey Executed by J. Gorlinski in 1872, and the Resurvey Executed by G.B. Hatch in 1966

Beginning at the standard corner of sections 34 and 35, T. 10 S., R. 4 W., monumented with an iron post, 2 1/2 inches diameter, firmly set in a mound of stone, with 2 ft. base, to top of brass cap, marked as described in the official record of the 1966 resurvey.

N. 89° 41.3' W., on the Second Standard Parallel South.

0.158

The closing corner of sections 2 and 3, T. 11 S., R. 4 W., monumented with an iron post, firmly set in a mound of stone, with 3 ft. base, to top of brass cap marked as described in the official record of the 1966 resurvey.

39.715

The standard 1/4 section corner of section 34, monumented with an iron post, 2 1/2 inches diameter, firmly set in a mound of stone, with 4 ft. base, to top of brass cap, marked as described in the official record of the 1966 resurvey.

N. 89° 45.7' W., beginning new measurement.

0.753

Point for the north 1/4 section corner of section 3 only, T. 11 S., R. 4 W., at midpoint between the two closing corners and on the Second Standard Parallel South. The 1966 resurvey monument was found lying loose on the ground.

Dependent Resurvey of a Portion of the South Boundary, (Second Standard Parallel South), T. 10 S., R. 4 W., Salt Lake Meridian, Utah

CHAINS	Reset the 1966 iron post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with brass cap marked as described in the official record of the 1966 resurvey.
39.749	The standard corner of sections 33 and 34, monumented with an iron post, 2 1/2 inches diameter, firmly set in a mound of stone, 3 ft. base, to top of brass cap marked as described in the official record of the 1966 resurvey.
39.749 20.425 40.850	From this corner, the closing corner of sections 3 and 4, T. 11 S., R. 4 W., monumented with an iron post, 2 1/2 inches diameter, firmly set in a mound of stone, with a 3 ft. base, to top of brass cap marked as described in the official record of the 1966 resurvey, bears S. 89° 47.7' W., 1.315 chs. distance.
	Dependent Resurvey of a Portion of the Subdivisional Lines, T. 10 S., R. 4 W., Salt Lake Meridian, Utah
	Reestablishment of the Survey Executed by J. Gorlinski in 1874, and the Resurvey Executed by G.B. Hatch in 1966
	From the corner of sections 11, 12, 13, and 14, monumented with an iron post, firmly set projecting 6 inches above ground, with brass cap marked as described in the official record of the 1966 resurvey.
	N. 0° 46.2' E., between sections 11 and 12.
20.425	Point for the S 1/16 section corner of sections 11 and 12; not monumented.
40.850	The 1/4 section corner of sections 11, and 12, monumented with an iron post, 2 1/2 inches diameter, projecting 6 inches above ground in a collar of stone, with brass cap, marked as described in the official record of the 1966 resurvey.
	From the standard corner of sections 34 and 35, on the south boundary of the township, hereinbefore described.
	N. 0° 12.5' W., between sections 34 and 35.
40.161	The 1/4 section corner of sections 34 and 35, monumented with an iron post, 2 1/2 inches diameter, firmly set, projecting 6 inches above ground, with brass cap marked as described in the official record of the 1966 resurvey.
	Set a 6 ft. steel fence post alongside the iron post.
	Set a 6 ft. steel fence post alongside the iron post.
8	

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

8	
CHAINS	N. 0° 04.5' E., beginning new measurement.
40.298	The corner of sections 26, 27, 34, and 35; monumented with an iron post, 2 1/2 inches diameter, firmly set, projecting 8 inches above ground, with brass cap marked as described in the official record of the 1966 resurvey.
	Set a 6 ft. steel fence post alongside the iron post.
40.192 40.110	From the 1/4 section corner of sections 26 and 35, monumented with an iron post, 2 1/2 inches diameter, firmly set, in a mound of stone, with 3 ft. base, to top of brass cap marked as described in the official record of the 1966 resurvey.
	Set a 6 ft. steel fence post alongside the iron post.
	N. 89° 33.8' W., between sections 26 and 35.
40.192	The corner of sections 26, 27, 34, and 35.
	N. 0° 11.0' W., between sections 26 and 27.
40.110	The 1/4 section corner of sections 26 and 27, monumented with an iron post, 2 1/2 inches diameter, firmly set, projecting 6 inches above ground, with brass cap marked as described in the official record of the 1966 resurvey.
	Set a 6 ft. steel fence post alongside the iron post.
	N. 0° 03.6' E., beginning new measurement.
40.212	The corner of sections 22, 23, 26, and 27, monumented with an iron post, 2 1/2 inches diameter, firmly set, projecting 2 inches above ground, with brass cap marked as described in the official record of the 1966 resurvey.
	From the 1/4 section corner of sections 23 and 26, monumented with an iron post, 2 1/2 inches diameter, firmly set, projecting 8 inches above ground, with brass cap marked as described in the official record of the 1966 resurvey.
	Set a 6 ft. steel fence post alongside the iron post.
	N. 89° 51.0' W., between sections 23 and 26.
20.223	Point for the W 1/16 section corner of sections 23 and 26.
20.223	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

CHAINS	
	T10S R4W
	W 1/16 <u>S23</u>
	s26
	1997
	Corner is located in a N and S fence line.
40.446	The corner of sections 22, 23, 26, and 27.
70.770	The corner of sections 22, 25, 20, and 27.
	N. 0° 15.9' E., between sections 22 and 23.
20.115	Point for the S 1/16 section corner of sections 22 and 23.
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with
	aluminum cap marked:
	alumnum cap marked:
	T10S R4W
	s 1/16
	S22 S23
	1997
	Corner is located in fence line, bears N and S.
	, , , , , , , , , , , , , , , , , , , ,
40.230	Ti- 1/4
40.230	The 1/4 section corner of sections 22 and 23, monumented with an iron post, 2 1/2 inches
	diameter, firmly set, projecting 6 inches above ground, with brass cap improperly marked
	(sections 22 and 23 are reversed).
	N. 0° 18.6' E., beginning new measurement.
40.287	The comment of marking 14, 15, 22, and 22, and and 1, 14, 15, 15, 15, 15, 15, 15, 15, 15, 15, 15
40.207	The corner of sections 14, 15, 22, and 23, monumented with an iron post, 2 1/2 inches
	diameter, firmly set, projecting 3 inches above ground, with brass cap marked as described in
	the official record of the 1966 resurvey.
	N. 0° 07.8' E., between sections 14 and 15.
20.070	Daint Cantha C 1/16 and the continue of the co
20.070	Point for the S 1/16 section corner of sections 14 and 15.
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with
	aluminum cap marked:
20.070	
	T10S R4W
	s 1/16
	S15 S14
	1007
	1997

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL Lines, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

CHAINS	Corner is located at the corner of fences, bearing S and W.
19.846	The 1/4 section corner of sections 14 and 15, monumented with a "T" iron, 3 inches below the surface of a dirt road and at the extension of fence intersection from the W and S. There is no evidence of the 1966 iron post. The "T" iron is accepted as the best available evidence of the original corner.
	At the corner point
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with aluminum cap marked:
	T10s R4W
	1/4 S15 S14
	1997
	Deposit the "T" iron and set a 6 ft. steel fence post alongside the aluminum post.
	From the corner of sections 11, 12, 13, and 14.
	S.89° 57.5' W., between sections 11 and 14.
19.846	Point for the E 1/16 section corner of sections 11 and 14.
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:
	T10s R4W
	E 1/16 S11
	\$14 1997
	aluminum cap marked: T10s R4W E 1/16
39.692	The 1/4 section corner of sections 11 and 14, monumented with an iron post, 2 1/2 inches diameter, firmly set, in a collar of stone, with brass cap marked as described in the official record of the 1966 resurvey.
	Set a 6 ft. steel fence post alongside the iron post.
39.692	From the corner of sections 10, 11, 14, and 15, monumented with an iron post, 2 1/2 inches diameter, firmly set in a mound of stone, to top of brass cap marked as described in the official

record of the 1966 resurvey.

N. 0° 19.4' E., between sections 10 and 11.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

CHAINS 20.149	Point for the S 1/16 section corner of sections 10 and 11.
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:
20.149 40.298 20.093 40.186	T10S R4W S 1/16 S10 S11 1996
	Set a 6 ft. steel fence post alongside the aluminum post.
40.298	The 1/4 section corner of sections 10 and 11, monumented with an iron post, 2 1/2 inches diameter, firmly set, projecting 3 inches above a mound of stone, with brass cap marked as described in the official record of the 1966 resurvey.
	Set a 6 ft. steel fence post alongside the iron post.
	From the 1/4 section corner of sections 33 and 34, monumented with an iron post, 2 1/2 inches diameter, firmly set in a mound of stone, 3 ft. base, to top of brass cap marked as described in the official record of the 1966 resurvey.
	N. 0° 11.4' E., between sections 33 and 34.
20.093	Point for the N 1/16 section corner of sections 33 and 34, not monumented.
40.186	The corner of sections 27, 28, 33, and 34, monumented with an iron post, 2 1/2 inches diameter, firmly set and projecting 8 inches above a collar of stone, with brass cap marked as described in the official record of the 1966 resurvey.
	Set a 6 ft. steel fence post alongside the iron post.
	From the corner of sections 26, 27, 34, and 35.
	N. 89° 49.8' W., between sections 27 and 34.
40.156	The 1/4 section corner of sections 27 and 34, monumented with an iron post, 2 1/2 inches diameter, firmly set in a collar of stone, with brass cap marked as described in the official record of the 1966 resurvey.
	Set a 6 ft. steel fence post alongside the iron post.
	Set a 6 ft. steel fence post alongside the iron post.
٠ ،	× I

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 10 S., R. 4 W., Salt Lake Meridian, Utah

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

8	
20.168 20.140 40.280 20.143	From the 1/4 section corner of sections 10 and 15, monumented with an iron post, 2 1/2 inches diameter, projecting 6 inches above the ground, with brass cap marked as described in the official record of the 1966 resurvey.
	Set a 6 ft. steel fence post alongside the iron post.
	S. 89° 57.7' W., between sections 10 and 15.
20.168	Point for the W 1/16 section corner of sections 10 and 15.
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:
	T10s R4W
	W 1/16 <u>S10</u>
	S15 1997
	Set a 6 ft. steel fence post alongside the aluminum post.
40.336	The corner of sections 9, 10, 15, and 16.
	N. 0° 06.4' E., between sections 9 and 10.
20.140	Point for the S 1/16 section corner of sections 9 and 10; not monumented.
40.280	The 1/4 section corner of sections 9 and 10, monumented with an iron post, 2 1/2 inches
	diameter, firmly set and projecting 4 inches above the ground, with brass cap marked as described in the official record of the 1966 resurvey.
	Set a 6 ft. steel fence post alongside the iron post.
	The Subdivision of Section 10, T. 10 S., R. 4 W., Salt Lake Meridian, Utah
	From the 1/4 section corner of sections 10 and 15. N. 0° 06.6' E., on the N-S center line of section 10.
	N. 0° 06.6' E., on the N-S center line of section 10.
20.143	Point for the center S 1/16 section corner of section 10.
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:
2 1	

THE SUBDIVISION OF SECTION 10, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

CHAINS	T10s R4W
	s 1/16 s10
	c 1997
	Set a 6 ft. steel fence post alongside the aluminum post.
	The corner is located 5 ft. north of E and W fence line.
40.006	
40.286	Point for the center 1/4 section corner of section 10, at intersection with the E-W center line of section 10.
40.286 80.731 40.450 60.617	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:
	T10s R4W
	C 1/4 S10
	1997
	Set a 6 ft. steel fence post alongside the aluminum post.
80.731	The 1/4 section corner of sections 3 and 10, monumented with an iron post, 2 1/2 inches
	diameter, firmly set and projecting 4 inches above the ground, with brass cap marked as
	described in the official record of the 1966 resurvey.
	Set a 6 ft. steel fence post alongside the iron post.
	From the 1/4 section corner of sections 10 and 11.
	S. 89° 57.3' W., on the E-W center line of section 10.
40.450	The center 1/4 section corner of section 10.
60.617	Point for the center W 1/16 section corner of section 10, not monumented.
	The 1/4 section corner of sections 9 and 10.
	From the S 1/16 section corner of sections 10 and 11.
	S. 89° 57.8' W., on the E-W center line of the SE 1/4 of section 10.
80.784 40.377	The center S 1/16 section corner of section 10.

THE SUBDIVISION OF SECTION 10, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

CHAINS	From the W 1/16 section corner of sections 10 and 15.
	N. 0° 06.5' E., on the N-S center line of the SW 1/4 of section 10.
20.142	Point for the SW 1/16 section corner of section 10, at intersection with the E-W center line of the SW 1/4 of section 10.
20.142 40.283	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:
	m10c pAw
	T10S R4W SW 1/16 S10
	1997
	Set a 6 ft. steel fence post alongside the aluminum post.
40.283	The point for the center W 1/16 section corner of section 10.
	From the center S 1/16 section corner of section 10.
	S. 89° 57.5' W., on the E-W center line of the SW 1/4 of section 10.
20.167 40.335	The SW 1/16 section corner of section 10.
40.335	The maint for the S. 1/16 and in a surrous for this or 0 and 10
70.555	The point for the S 1/16 section corner of sections 9 and 10.
	The Subdivision of Section 11, T. 10 S., R. 4 W., Salt Lake Meridian, Utah
	T. To S., R. 4 W., Sait Lake Worklan, Clair
	From the 1/4 section corner of sections 11 and 14.
	N. 0° 14.3' E., on the N-S center line of section 11.
20.461	Point for the center S 1/16 section corner of section 11.
20.461	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, in a collar of stone, with aluminum cap marked:
	T10s R4W
	Ċ Ç
	s 1/16 s11
	1997
	Set a 6 ft. steel fence post alongside the aluminum post.

THE SUBDIVISION OF SECTION 11, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

CHAINS 40.922	Point for the center 1/4 section corner of section 11, at intersection with the E-W center line of section 11.
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:
	T10S R4W C 1/4 S11
	1997 Set a 6 ft. steel fence post alongside the aluminum post.
40.922 81.306 20.033 40.066 80.291	The 1/4 section corner of sections 2 and 11, monumented with an iron post, 2 1/2 inches diameter, firmly set in a mound of stone to top of brass cap marked as described in the official record of the 1966 resurvey.
	Set a 6 ft. steel fence post alongside the iron post.
	From the 1/4 section corner of sections 11 and 12.
	N. 89° 56.0' W., on the E-W center line of section 11.
20.033	Point for the center E 1/16 section corner of section 11, not monumented.
40.066	The center 1/4 section corner of section 11.
80.291	The 1/4 section corner of sections 10 and 11.
	From the E 1/16 section corner of sections 11 and 14.
	N. 0° 30.2' E., on the N-S center line of the SE 1/4 of section 11.
20.443	Point for the SE 1/16 section corner of section 11, at intersection with the E-W center line of the SE 1/4 of section 11.
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:
	aluminum cap marked: T10S R4W SE 1/16 S11 1997

THE SUBDIVISION OF SECTION 11, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

CHAINS	Set a 6 ft. steel fence post alongside the aluminum post.
40.886	The point for the center E 1/16 section corner of section 11.
	From the point for the S 1/16 section corner of sections 11 and 12.
	N. 89° 59.3' W., on the E-W center line of the SE 1/4 of section 11.
19.940	The SE 1/16 section corner of section 11.
39.880	The center S 1/16 section corner of section 11.
	From the center S 1/16 section corner of section 11.
	N. 89° 29.2' W., on the E-W center line of the SW 1/4 of section 11.
40.257	The S 1/16 section corner of sections 10 and 11.
40.886 19.940 39.880 40.257	The Subdivision of Section 15, T. 10 S., R. 4 W., Salt Lake Meridian, Utah
	From the 1/4 section corner of sections 15 and 22.
	N. 0° 08.1' W., on the N-S center line of section 15.
19.998	Point for the center S 1/16 section corner of section 15.
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:
	T10s R4W
	s 1/16 s15
	C 1997
	Corner is located at fence corner, with fences bearing N and E.
39.996	Point for the center 1/4 section corner of section 15, at intersection with the E-W center line of section 15.
39.996	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:
. 8	S

THE SUBDIVISION OF SECTION 15, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

CHAINS	TIOS DAW
	T10S R4W C 1/4 S15
	1997
80.319 40.360 80.771 40.270	Corner is located at fence corner, with fences bearing W and S.
80.319	The 1/4 section corner of sections 10 and 15.
	From the 1/4 section corner of sections 14 and 15.
	S. 89° 58.2' W., on the E-W center line of section 15.
	or of the box of the box of section 13.
40.360	The center 1/4 section corner of section 15.
80.771	The 1/4 section corner of sections 15 and 16.
	From the S 1/16 section corner of sections 14 and 15.
	N. 89° 55.6' W., on the E-W center line of the SE 1/4 of section 15.
40.270	775
40.270	The center S 1/16 section corner of section 15.
	Dependent Resurvey of a Portion of the Subdivision of
	Section 23, T. 10 S., R. 4 W., Salt Lake Meridian, Utah
	Reestablishment of the Survey Executed by Glen B. Hatch in 1966
	From the 1/4 restion serves of restions 22 and 26
	From the 1/4 section corner of sections 23 and 26.
	N. 0° 12.1' E., on the N-S center line of section 23.
2	
20.112	Point for the center S 1/16 section corner of section 23, not monumented.
40.224	
40.224	The center 1/4 section corner of section 23, monumented with an iron post, 2 1/2 inches diameter, firmly set and projecting 5 inches above ground, with brass cap marked as described
	in the official record of the 1966 survey.
20.112 40.224 20.198	Corner is located 6 ft. S of an E and W fence line.
	N. 89° 50.6' W., on the E-W center line of section 23.
20.198	Point for the center W 1/16 section corner of section 23, not monumented.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISION OF SECTION 23, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

CHAINS 40.396	The 1/4 section corner of sections 22 and 23.
40.396 20.113	The Subdivision of the SW 1/4 of Section 23, T. 10 S., R. 4 W., Salt Lake Meridian, Utah
	From the W 1/16 section corner of sections 23 and 26.
	N. 0° 14.0′ E., on the N-S center line of the SW 1/4 of section 23.
20.113	Point for the SW 1/16 section corner of section 23, at intersection with the E-W center line of the SW 1/4 of section 23.
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:
	M10C DAM
	T10S R4W
	SW 1/16 S23 1997
	1997
	Corner is located at fence corner, with fences bearing W and S.
40.227	The point for the center W 1/16 section corner of section 23.
	From the point for the center S 1/16 section corner of section 23.
	N. 89° 50.8' W., on the E-W center line of the SW 1/4 of section 23.
20.210	The SW 1/16 section corner of section 23.
20.210 40.421	The S 1/16 section corner of sections 22 and 23.
	The Subdivision of Section 26, T. 10 S., R. 4 W., Salt Lake Meridian, Utah
	From the 1/4 section corner of sections 26 and 35.
	N. 0° 07.6' E., on the N-S center line of section 26.
40.329	Point for the center 1/4 section corner of section 26, at intersection with the E-W center line of section 26.
40.329	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with aluminum cap marked:

THE SUBDIVISION OF SECTION 26, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

CHAINS		
	T10s R4W	
	C 1/4 S26	
	1997	
	1001	
80.524 40.702 60.903	Corner is located in an E and W fence line.	
	Corner is located in an E and w lence line.	
00.504		
80.524	The 1/4 section corner of sections 23 and 26.	
	From the 1/4 section corner of sections 25 and 26, monumented with an iron post, 2 1/2 inches	
	diameter, firmly set and projecting 4 inches above ground, with brass cap marked as described	
	in the official record of the 1966 resurvey.	
	· · · · · · · · · · · · · · · · ·	
	Corner is located in an E and W 4 strand barb wire fence line.	
	Corner is located in an it and w 4 straint party wire lence line.	
	N 000 50 51 W	
	N. 89° 52.5' W., on the E-W center line of section 26.	
40.702	The center 1/4 section corner of section 26.	
60,903	Point for the center W 1/16 section corner of section 26.	
00.705	a 1 one for the content w 1710 section corner of section 20.	
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with	
	aluminum cap marked:	
	T10s R4W	
	c <u>W 1/16</u> c	
	S26	
	1997	
	Corner is located at fence corner, with fences bearing N and E.	
	Corner is located at lonce corner, with lences bearing 14 and c.	
04 404		
81.104	The 1/4 section corner of sections 26 and 27.	
	From the center W 1/16 section corner of section 26.	
	N. 0° 05.6' E., on the N-S center line of the NW 1/4 of section 26.	
40.204		
70.207	The W 1/16 corner of sections 23 and 26.	
	The Subdivision of Section 34,	
	T. 10 S., R. 4 W., Salt Lake Meridian, Utah	
40.204		
	From the standard 1/4 section corner of section 34, hereinbefore described.	
	- ·,	
	N. 0° 23.4' W., on the N-S center line of section 34.	
	N. 0° 23.4' W., on the N-S center line of section 34.	
× (2	

THE SUBDIVISION OF SECTION 34, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

3	
60.248 80.364 39.837 60.224	Point for the center 1/4 section corner of section 34, at intersection with the E-W center line of section 34.
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 20 inches in the ground to bedrock, and in a collar of stone, with aluminum cap marked:
	T10s R4W
	C 1/4
	s34
	1997
	Corner is located 37 ft. east of a fence, bears N and S, and 86 ft. north of a fence, bears E and W.
60.248	Point for the center N 1/16 section corner of section 34.
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 3 inches in the ground to bedrock, in a mound of stone, 4 ft. base to top of aluminum cap marked:
	T10s R4W
	Ç
	N 1/16 S34
	C 1007
	1997
80.364	The 1/4 section corner of sections 27 and 34.
	From the 1/4 section corner of sections 34 and 35.
	N. 89° 44.0' W., on the E-W center line of section 34.
39.837	The center 1/4 section corner of section 34.
60.224	Point for the center W 1/16 section corner of section 34, not monumented.
80.611	The 1/4 section corner of sections 33 and 34.
	From the point for the center W 1/16 section corner of section 34.
	N. 0° 05.9' W., on the N-S center line of the NW 1/4 of section 34.
80.611 20.105	Point for the NW 1/16 section corner of section 34, at intersection with the E-W center line of the NW 1/4 of section 34.

THE SUBDIVISION OF SECTION 34, T. 10 S., R. 4 W., SALT LAKE MERIDIAN, UTAH

CHAINS	
	Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 20 inches in the ground to
	bedrock, in a mound of stone, 3 ft. base to top of aluminum cap marked:
	T10s R4W
	NW 1/16
	S34
	1997
40.210	The W 1/16 section corner of sections 27 and 34.
	From the center N 1/16 section corner of section 34.
	N. 89° 46.0' W. on the E-W center line of the NW 1/4 of section 34.
20.285	The NW 1/16 section corner of section 34.
40.570	The point for the N 1/16 section corner of sections 33 and 34.
40.210 20.285 40.570	

United States
Department of the Interior
Bureau of Land Management

FIELD ASSISTANTS

Name Name	Capacity
Ronald K. Baugh Steven Oatman Nathan James	Supervisory Cadastral Surveyor Survey Technician Survey Technician

CERTIFICATE OF SURVEY

I, M. Ross Workman, Supervisory Cadastral Surveyor, hereby certify upon honor that, in pursuance of special instructions bearing the date of the 1st day of August, 1996, I have dependently resurveyed a portion of the south boundary, a portion of the subdivisional lines and subdivided sections 10, 11, 15, 23, 26, and 34, in Township 10 South, Range 4 West,

of the Salt Lake Meridian, in the State of Utah, which are represented in the foregoing field notes as having been executed by me and under my direction; and that said survey has been made in strict conformity with said special instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in specific manner described in the foregoing field

March 16, 1998	M. Ross Workers am
Date	(Supervisory Cadastral Surveyor)
Date	(Cadastral Surveyor)
	TIFICATE OF APPROVAL
1	BUREAU OF LAND MANAGEMENT Salt Lake City, Utah
The foregoing field notes of the depend subdivisional lines and the subdivision Salt Lake Meridian, Utah,	ent resurvey of a portion of the south boundary, and a portion of the of sections 10, 11, 15, 23, 26, and 34, Township 10 South, Range 4 West,
executed by M. Ross Workman, Super	visory Cadastral Surveyor
having been critically examined and fou	and correct, are hereby approved.
March 18, 1998	Line W. Well

(Chief Cadastral Surveyor for Utah)

Date